

## **21. Sewer system repairs to the Sugar Creek Basin.**

**HISTORY:** City Staff discovered that the Sugar Creek 30" gravity trunk line had deteriorated and failed which caused the sewer to run over into the Sugar Creek Basin.

**Status: Ongoing**

## **22. Repairs for the Sugar Creek Armoring and Gornto/Force Main Stabilization.**

**HISTORY:** City Staff discovered that during the severe rain event which occurred on November 7, 2024, the stream bank of Sugar Creek had destabilized and eroded. This rapid bank destabilization and erosion exposed the 30" ductile iron Gornto Road Force Main in such away that put the city at substantial risk of an environmental disaster. The decision was made by City Staff to reconstitute and armor the bank to protect the Force Main adequately from damage and failure due to impact of weathering.

**Status: Completed**

