## 2. CONTINUING VIOLATIONS

Violation	Description	Inspection#	Date
192.619(a)	No person may operate a segment of steel or plastic pipeline at a pressure that exceeds a maximum	LB17-020	5/15/2017

## 3. CLEARED VIOLATIONS

## 4. NEW VIOLATIONS

Violation	Description	Inspection#	Date
192.617	Investigation of failures.	DL19-004	1/1/2019
192.614(a)	Except for pipelines listed in paragraphs (d) and (e) of this section, each operator of a buried	DL19-004	1/1/2019
192.615(a)(3) (i)	Prompt and effective response to a notice of each type of emergency, including the following	DL19-004	1/1/2019
199.105(c)(2)	Post-accident testing; If a test required by this section is not administered within the	DL19-004	1/1/2019
199.225(a)(1)	Post-accident; As soon as practicable following an accident, the Company must test each surviving	DL19-004	1/1/2019

## 5. OTHER RECOMMENDATIONS/COMMENTS

SEE ATTACHED INSPECTION REPORT