

Permittee shall submit to the Director, a RCRA Facility Investigation Workplan pursuant to Condition IV.F.

IV.D. Verification Investigation

1. The Director may require the Permittee to submit a Verification Investigation (VI) Workplan for any SWMU or AOC discovered under Condition IV.A.2 in a schedule to be determined by the Director. The VI Workplan shall describe all actions necessary to verify the presence or absence of a release for any SWMU or AOC. The VI Workplan shall include a schedule of implementation, which includes intermediate milestones beginning with the Permittee's receipt of the Director's written approval of the VI Workplan continuing through submission of the VI Report required by Condition IV.D.3.
2. Upon receipt of the Director's written approval of the VI Workplan, the Permittee shall implement the Workplan in accordance with the schedule of implementation contained therein.
3. The Permittee shall submit a VI report in accordance with the schedule of implementation contained within the approved VI Workplan. The VI Report shall describe all actions taken to verify the presence or absence of releases including all data collected during the VI. The Director shall review the VI Report and notify the Permittee in writing of the need for further investigation, interim measures and/or corrective action pursuant to Condition IV.E., IV.F., and/or IV.G., or of a finding of no further action required.

IV.E. Interim Measures (IM)

1. Upon the Director's concurrence, the Permittee may conduct interim measures to contain, remove, or treat contamination resulting from releases from any SWMU or AOC as necessary to protect human health and the environment. Such interim measures may be conducted concurrently with any investigations required by this permit.
2. Within thirty (30) days of the Permittee's determination that interim measures are necessary, or within thirty (30) days of receipt of the Director's written notice that interim measures are necessary, the Permittee shall submit to the Director an Interim Measures Workplan. The IM Workplan shall describe all measures necessary to contain, remove or treat contamination resulting from releases from any SWMU or AOC. The IM Workplan shall include a schedule of implementation, which includes intermediate milestones beginning with the Permittee's receipt of the Director's written approval of the IM Workplan and continuing through submission of the IM Report required by Condition IV.E.5.
3. Upon receipt of the Director's written approval of the IM Workplan, the Permittee shall implement the Workplan in accordance with the schedule of implementation contained therein.
4. The Permittee shall provide written notice to the Director as soon as possible of any planned changes, reductions or additions to the interim measures described in the IM Workplan.
5. The Permittee shall submit an IM Report in accordance with the schedule of implementation contained in the approved IM Workplan. The IM Report shall describe all interim measures taken to contain, remove or treat contamination resulting from releases from any SWMU or AOC. The IM Report shall also provide a summary of all data or other information obtained during implementation of the IM Workplan and a summary of the effectiveness of the interim measures in achieving the objective of Condition IV.G.