

# Solutions without massive infrastructure:

## Limiting withdrawals

- WMD permit standard conditions can require withdrawal limits, as in [Phase II, III, IV Water Shortage](#)
- In November 2025, a SRWMD Board member asked for preparation for dryer and hotter
- Eventually: limit permits issued

