
**Figure 1.** Location of a fish kill that occurred in Sugar Creek and the Withlacoochee Rover in Valdosta, Georgia on December 10, 2019



- Site 1: Above Kill Area
- Site 2: Sewage Spill Site on Sugar Creek
- Site 3: Baytree Rd and Sugar Creek
- Site 4: Stopping Point of Upper Count on Sugar Creek
- Site 5: Gornto Rd and Sugar Creek
- Site 6: Upper point of Lower Count on Sugar Creek
- Site 7: Withlacoochee River above the confluence of Sugar Creek
- Site 8: Confluence of Sugar Creek and Withlacoochee River
- Site 9: Stopping Point of Upper Count on Withlacoochee River
- Site 10: Upper Point of Lower Count on Withlacoochee River
- Site 11: GA Highway 133
- Site 12: Lower End of Fish Kill