Pipeline Construction Progress Photos



Photo 9: Verbena Loop. View of restored rightof-way around the WCN14C030 wetland crossing. Facing east.



Photo 10: Verbena Loop. View of restored rightof-way from the Access Road 2 crossing. Facing east.