





Figure 3-6: Results of Assimilative Capacity Assessment – DO under Current Permit Conditions


SUWANNEE-SATILLA BASIN




SUWANNEE BASIN



SATILLA BASIN



ST. MARYS BASIN



SUWANNEE-SATILLA