



## **17. Repairs to gravity sewer main on River Street.**

**HISTORY:** A contractor was contacted to mobilize, establish, and maintain the by-pass for the gravity sewer main on River Street that had been compromised and severed due to the flooding and the erosion of the creek bank.

**Status: Completed**

## **18. Sewer repairs on Pebblewood Drive.**

**HISTORY:** A contractor was contacted to mobilize to establish and maintain a bypass for the 18" gravity sewer main that had been blocked/possibly collapsed.

**Status: Completed**

