



Figure 2: 09/06/2025. Submerged aquatic vegetation primarily consists of filamentous algae. Loss of soil around pilings beneath private dock at 218 SW Riverside Ave, Fort White, FL.